SAFE CLEANING OF LEAD PAINT CHIPS AND DUST

Step one:

Prepare Supplies

PREPARE. Gather rubber gloves, throw-away wipes or towels, garbage bags, spray bottle with soap and water, and mop. PUT ON RUBBER GLOVES. If you do DON"T USE A VACUUM UNLESS

not have rubber (or disposable) gloves, you will need to wash your hands well after cleaning.

USE SUPPLIES YOU CAN THROW AWAY. Use soapy cleaners or products made to remove lead dust.

IT IS A HEPA VACUUM. A regular vacuum will spread lead dust into the air.



STEP TWO: Remove **Paint Chips**

2

REMOVE PAINT CHIPS.

Window areas and porches often have peeling paint and lead dust. Pick up the paint chips you can see and throw them away in a plastic bag.



STEP THREE: Wet & Wipe Surfaces

ALWAYS SPRAY WINDOW SILLS WIH SOAP AND WATER AND WE-MOP FLOORS. Do not use a broom to sweep lead dust. Throw away wipes after cleaning each area.



STEP FOUR: Mop

MOP with a disposable mop head or paper towel to wipe away suds.





STEP FIVE: Clean Often

CHANGE TOWELS OFTEN until no paint chips, dust, or dirt can be seen. Put garbage in a plastic bag, and seal with tape or a knot. The sealed bag can be disposed of with normal trash for pickup

REPEAT THESE STEPS WEEKLY, or when dirt and dust appear on floors, porches, window wells, window sills, stairs, or children's play areas.





For more information, visit: https://www.health.ny.gov/environmental/lead/,

or call The Sullivan County Public Health Services Lead Poisoning Prevention Program at: 845-292-5910, Ext. 0.